

TCODE	PGMNA	TTEXT
Q000	MENUQ000	Quality management
QA00	MENUQA00	Quality inspection
QA01	SAPLQPL1	Create Inspection Lot
QA01A	SAPLQPL1	Create Inspection Lot
QA02	SAPLQPL1	Change Inspection Lot
QA02A	SAPLQPL1	Change Inspection Lot
QA03	SAPLQPL1	Display inspection lot
QA05	RQJBCTRL	Job planning: Periodic inspection
QA06	RQJBCTRL	Job overview: Periodic inspection
QA07	RQAAAS10	Trigger for recurring inspection
QA07L	RQBALDSP	Deadline Monitoring Log
QA08	RQMQMM00	Collective Processing of Insp. Setup
QA09	SAPMSNUM	No. range maintenance for insp.lots
QA10	RQEVAI30	Trigger automatic usage decision
QA10L	RQBALDSP	Log for Automatic Usage Decision
QA11	SAPMQEVA	Record usage decision
QA12	SAPMQEVA	Change usage decision with history

QA13	SAPMQEVA	Display usage decision	
QA14	SAPMQEVA	Change UD without history	
QA16	RQEVAI10	Collective UD for accepted lots	
QA17	RQJBCTRL	Job planning for auto usage decision	
QA18	RQJBCTRL	Job overview for auto usage decision	
QA19	RQEVAI30	Automatic usage decision	
QA22	RQAPPU10	Change inspection point quantities	
QA23	RQAPPU10	Display insp.point quantities	
QA32	RQEEAL10	Change data for inspection lot	
QA32WP	RQEEAW10	QA32 -Call from Workplace/MiniApp	
QA33	RQEEAL10	Display data for inspection lot	
QA40	RQEVAI50	Auto. Usage Decision for Production	
QA40L	RQBALDSP	Log for Automatic Usage Decision	
QA41	RQJBCTRL	Scheduling UD for Production Lots	
QA42	RQJBCTRL	Job planning: UD prod. insp.lots	
QA51	RQJBCTRL	Scheduling Source Inspections	
QA52	RQJBCTRL	Source inspections: Job overview	
QAC1	SAPLQPL1	Change insp. lot actual quantity	
QAC2	SAPLQPL1	Transfer stock to insp. lot	
QAC3	SAPLQPL1	Reset sample	

QAER	SAPLOPTI	Display archive objects	
QAS1	RQEIFM10	Download Insp. Specs. (Obsolete)	
QAS2	RQEIFM20	Download Basic Data (Obsolete)	
QAS3	RQEIFM50	Upload Results (Obsolete)	
QAS4	RQEIFM60	Upload UD (Obsolete)	
QC01	SAPMQCPA	Create certificate profile	
QC02	SAPMQCPA	Change certificate profile	
QC03	SAPMQCPA	Display certificate profile	
QC06	RQCQCD01	Immediate delete of cert. profiles	
QC11	SAPMV13I	Create cert. profile assignment	
QC12	SAPMV13I	Change cert. profile assignment	
QC13	SAPMV13I	Display cert. profile assignment	
QC14	SAPMV13I	Create cert.prof.assign.w/copy model	
QC15		Create cert. profile assignment	
QC16		Change cert. profile assignment	
QC17		Display cert. profile assignment	
QC18		Create cert.prof.assign.w/copy model	
QC20	RQCAAP03	Certificates for Deliveries	
QC21	RQCAAP01	Quality certificate for the insp.lot	
QC22	RQCAAP02	Quality Certificate for Batch	

QC31	RQCARD03	Archive display: Delivery item	
QC32	RQCARD01	Archive display: Inspection lot	
QC40	SAPLQC07	Internet Certificate for Delivery	
QC40A	SAPLQC07	Internet Certificate for Delivery	
QC42	SAPMQCWA	Batch certificate on WWW	
QC51	SAPMQCPR	Create certificate in procurement	
QC52	SAPMQCPR	Change certificate in procurement	
QC53	SAPMQCPR	Display certificate in procurement	
QC55	RQCPRM10	Worklist: Certificates - Procurement	
QCC0	RQIMGALL	QM: Direct Access to IMG	
QCC1	RQIMG010	Direct Access to IMG: Notification	
QCC2	RQIMG020	IMG Direct Access: QM Q-Notification	
QCC3	RQIMG030	IMG Direct Access: QM Q-Inspection	
QCC4	RQIMG040	IMG Direct Access: QM Q-Planning	
QCC5	RQIMG050	IMG Direct Selection: QM Bus. Add-In	
QCCC		QM standard settings complete	
QCCF		QM standard forms	
QCCK		QM standard settings: Catalogs	
QCCM		QM std. settings: Qual. notifs.	
QCCN		QM standard number ranges	

QCCP		QM std. settings: Quality planning	
QCCS		QM sampling schemes	
QCCT		QM standard texts	
QCCU		QM standard settings: Environment	
QCCW		QM std. settings: Quality inspection	
QCCY		Transport QM tolerance key	
QCCZ		QM std. settings: Qual. certificates	
QCC_STABI		Copy Stability Study Customizing	
QCC_STABI_NK		Copy Stability Study Number Ranges	
QCE2	SAPLQCE2	Edit Communication Support	
QCE3	SAPLQCE2	Display Communication Support	
QCHECK	QUERY_CHECK	Check Query	
QCMS	RQCAAPMS	Certificate for Inspection Lot w. MS	
QCYF	RSTXFCPY	QM standard forms (general)	
QCYT	RSTXTCPY	QM standard texts (general)	
QD21	RQARCQM3	Mark completed notifications	
QD22		Archiving Notifications: Archive	
QD24		Archiving Notifications: Delete	
QD25		Archiving Notifications: Admin.	
QD33	RQARCQDL	Delete quality level	

QD34	RQJBCTRL	Delete quality level planning	
QD35	RQJBCTRL	Delete job overview for Q-levels	
QDA1		Edit sampling type	
QDA3		Display sampling type	
QDB1		Maintain allowed relationships	
QDB3		Display allowed relationships	
QDH1	RQDAAM10	Q-level evaluation: Change data	
QDH2	RQDAAM10	Q-level evaluation: Display data	
QDL1	SAPMQDQL	Create quality level	
QDL2	SAPMQDQL	Change quality level	
QDL3	SAPMQDQL	Display quality level	
QDM1		Edit valuation mode	
QDM3		Display valuation mode	
QDP1	SAPMQDSP	Create sampling scheme	
QDP2	SAPMQDSP	Change sampling scheme	
QDP3	SAPMQDSP	Display sampling scheme	
QDR1	SAPMQDDR	Create dynamic modification rule	
QDR2	SAPMQDDR	Change dynamic modification rule	
QDR3	SAPMQDDR	Display dynamic modification rule	
QDR6	RQDULM20	Disp. where-used list-dyn. mod. rule	

QDR7	RQDULM20	Replace dynamic mod. rule used	
QDV1	SAPMQDSV	Create sampling procedure	
QDV2	SAPMQDSV	Change sampling procedure	
QDV3	SAPMQDSV	Display sampling procedure	
QDV6	RQDULM10	Uses: Sampling procedures	
QDV7	RQDULM10	Replace sampling procedure used	
QE00	MENUQE00	Quality Planning	
QE01	SAPMQEEA	Record characteristic results	
QE02	SAPMQEEA	Change characteristic results	
QE03	SAPMQEEA	Display characteristic results	
QE04	SAPMQEEA	Record sample results	
QE05	SAPMQEEA	Change sample results	
QE06	SAPMQEEA	Display sample results	
QE09	SAPMQEEA	Indiv.display of charac.result	
QE09WP	RQE09WP	Call QE09 from Workplace	
QE11	SAPMQEEA	Record results for inspection point	
QE12	SAPMQEEA	Change results for inspection point	
QE13	SAPMQEEA	Display results for inspection point	
QE14	SAPMQEEA	Record results for delivery note	
QE15	SAPMQEEA	Change results for delivery note	

QE16	SAPMQEEA	Display results for delivery note	
QE17	SAPMQEEA	Record results for equipment	
QE18	SAPMQEEA	Change results for equipment	
QE19	SAPMQEEA	Display results for equipment	
QE20	SAPMQEEA	Record results for funct. location	
QE21	SAPMQEEA	Change results for funct. location	
QE22	SAPMQEEA	Display results for funct. location	
QE23	SAPMQEEA	Record results for phys. sample	
QE24	SAPMQEEA	Change results for phys. sample	
QE25	SAPMQEEA	Display results for phys. sample	
QE29	SAPMSNUM	No. Range Maint.: Conf. No. for Char	
QE51	RQEEAM10	Results recording worklist	
QE51N	SAPLQEEA	Results Recording Worklist	
QE52	RQEEAM20	Worklist: Results for phys. sample	
QE53	RQEEAM30	Worklist: Record results for equip.	
QE54	RQEEAM40	Worklist: Results for funct. loctns	
QE71	RQETBM10	Tabular res. recording for insp. pts	
QE72	RQETBM20	Tabular Results Rec. for Insp. Lots	
QE73	RQETBM30	Tabular res. recording for characs.	
QEDS	RQEEAMDS	Signature Process	

QEH1	SAPLQEH1	Worklist for Mobile Results Rec.	
QEI1	RQEIFML1	Displaying QM Interfaces Appl. Log	
QEI2	RQEIFML2	Deleting QM Interfaces Appl. Log	
QEW01	RQEWWM10	Results Recording on Web	
QEW01V	RQEWWM00	Variant Maint.: Recording on Web	
QF01	SAPMQFFE	Record defect data	
QF02	SAPMQFFE	Change defect data	
QF03	SAPMQFFE	Display defect data	
QF11	SAPMQFFE	Record defects for inspection lot	
QF21	SAPMQFFE	Record defects for operation	
QF31	SAPMQFFE	Record defects for characteristic	
QF4	QUERY_F4_GET	Available queries	
QF41_WD	SAPMQFFE	Record Defects for Char./Insp. Point	
QG09	SAPMSNUM	Maint. num. range Q control charts	
QGA1	RQGAAG10	Display quality score time line	
QGA2	RQGAAM20	Display inspection results	
QGA3	RQGAAM31	Print inspection results	
QGA4	SAPLQG_EVAL	General QM Evaluations	
QGC1	RQERKM10	Qual. control charts for insp. lots	
QGC2	RQERKM20	Control charts for task list charac.	

QGC3	RQERKM30	Control charts for master insp. char
QGD1	RIEQUI20	Test Equipment Usage List
QGD2	RQTETR00	Test Equipment Tracking
QGP1	RQGEPM10	Results history for task list charac
QGP2	RQGEPM10	Results History for Task List Charac
QI01	SAPMQBAA	Create quality info. - purchasing
QI02	SAPMQBAA	Change qual.information - purchasing
QI03	SAPMQBAA	Display quality info. - purchasing
QI04	RQJBCTRL	Job planning for QM procurement keys
QI05	RQBAAM50	Mass maintenance QM procurement keys
QI06	RQBAAM10	QM Releases: Mass maintenance
QI07	RQBAAM20	Incoming insp. and open pur. orders
QI08	RQJBCTRL	Job overview of QM procurement keys
QISR	SAPQISRW	Internal Service Request
QISR1	SAPLQISR3	Internal Service Request - Forms
QISRACTIVITY	QISRACTIVITY	ISR Activity
QISRCONF	SAPLQISR_WIZARD_FW	ISR Wizard Initial Screen
QISRLIST	SAPLQISR_WIZARD_FW	ISR Wizard: List of Scenarios
QISRSCENARIO		Customizing Szenario
QISRSCENARIO_OVS		ISR Scenario - Extended Search Help

QISRTRANSPORT	SAPLQISR8	ISR Customizing Transport	
QISRW	SAPQISRW	Internal Service Request on the Web	
QISR_BCK		ISR: Popup for Editing in the Portal	
QISR_PCR60	QISR_PCR	vc_scenario for Message type 60(PCR)	
QISR_SM29		ISR Customizing: Table Transfer	
QISR_SR12_START	SAPMSR12_START	Suggestion System	
QI_DISPLAY_PLAN	RPLM_QI_DISPLAY_PLAN	Display Task List	
QK01	RQECOM10	Assign QM order to material	
QK02	RQECOM20	Display assigned QM orders	
QK03		Maintain Specs for Order Type	
QK04	RQECOM40	Create QM order	
QK05	RQECOM30	Confirmed activities for insp. lot	
QL11	RBDSEQMAT	Mat: Distribute Inspection Setup-ALE	
QL21	RBDSEQPMK	Master Inspection Characs (ALE)	
QL31	RBDSEQSMT	Distribute Inspection Methods (ALE)	
QL41	RBDSEQPGR	Distribute Code Groups (ALE)	
QM00	MENUQM00	Quality Notifications	
QM01	SAPLIQS0	Create quality notification	
QM02	SAPLIQS0	Change quality notification	
QM03	SAPLIQS0	Display quality notification	

QM10	RQMELL10	Change list of quality notifications
QM10WP	RQMELW10	QM10 - Call from Workplace/MiniApp
QM11	RQMELL10	Display List of Qual. Notifications
QM12	RQMELL20	Change list of tasks
QM13	RQMELL20	Display list of tasks
QM13WP	RQMELW20	QM13 - Call from Workplace/MiniApp
QM14	RQMELL30	Change list of items
QM15	RQMELL30	Display list of items
QM16	RQMELL40	Change activity list
QM17	RQMELL40	Display activity list
QM19	RQMELM10	List of Q Notifications, Multi-Level
QM50	RQMAAG10	Time line display Q notifications
QMW1	SAPQMWWW	Create quality notification (WWW)
QM_FMEA		FMEA Cockpit
QM_FMEAMONITOR	PLM_FMEA_MONITOR	FMEA Monitor
QM_FMEA_DISPLAY	QM_FMEA_DISPLAY	Display FMEA
QM_FMEA_RESIDENCE		FMEA: Determine Residence Duration
QP01	SAPLCPDI	Create Inspection Plan
QP02	SAPLCPDI	Change Inspection Plan
QP03	SAPLCPDI	Display Inspection Plan

QP05	RQPDRK00	Print inspection plan	
QP06	RQBAAM40	List: Missing/unusable insp. plans	
QP07	RQBAAM30	List: Missing/Unusable GR InspPlans	
QP08	RQPDRK02	Print task lists for material	
QP11	SAPLCPDI	Create reference operation set	
QP12	SAPLCPDI	Change reference operation set	
QP13	SAPLCPDI	Display reference operation set	
QP21S	SAPLQMIP_IP_MAINTAIN_UI	Create Inspection Plan from a Source	
QP48	SAPMSNUM	Number Ranges for Physical Samples	
QP49	SAPMSNUM	Number range for phys. samp. drawing	
QP60	RMPLAN00	Time-related development of plans	
QP61	RCPCD006	Display change documents insp.plan	
QP62	RCPCD003	Change documents ref.operation sets	
QPCG	RQMIP_SPECIP_MATCHING	Synchr. Insp. Plan from Ext. Source	
QPCP	SAPLQPCP_UI	Control Plan	
QPCP_NUM		Number Range for Control Plan	
QPIQS8	RQVIQS8	QM MiniApp Selection Variant	
QPIQS9	RQVIQS9	QM MiniApp Selection Variant	
QPNQ	SAPMSNUM	Number ranges for inspection plans	
QPQA32	RQVQA32	QM MiniApp Selection Variant	

QPQGC1	RQVQGC1	QM MiniApp Selection Variant	
QPQM10	RQVQM10	QM MiniApp Selection Variant	
QPQM13	RQVQM13	QM MiniApp Selection Variant	
QPR1	SAPLQPRS	Create physical sample	
QPR2	SAPLQPRS	Change Sample	
QPR3	SAPLQPRS	Display physical sample	
QPR4	SAPLQPRS	Confirm physical sample drawing	
QPR5	RQPRLS10	Manual inspection lots for physSamps	
QPR6	RQPRSS10	Create new phys.-samp. drawing w.ref	
QPR7	RQPRSS30	Storage Data Maintenance	
QPV2	SAPLQPRV	Maintain sample drawing procedure	
QPV3	SAPLQPRV	Display sample drawing procedure	
QS21	SAPMQSDA	Create master insp. characteristic	
QS21S	SAPLQMIP_MIC_UI	Create Master Insp.Char. from Source	
QS22	SAPMQSDA	Create master insp. charac. version	
QS23	SAPMQSDA	Change master insp. charac. version	
QS24	SAPMQSDA	Display master insp. charac. version	
QS25	SAPMQSDA	Delete master insp. charac. version	
QS26	SAPMQPDA	Display characteristic use	
QS27	SAPMQPDA	Replace master insp. characteristic	

QS28	RQPMKV10	Display insp. charac. list	
QS29	SAPMSNUM	Maintain characteristic number range	
QS31	SAPMQSCA	Create inspection method	
QS32	SAPMQSCA	Create inspection method version	
QS33	SAPMQSCA	Change inspection method version	
QS34	SAPMQSCA	Display inspection method version	
QS35	SAPMQSCA	Delete inspection method version	
QS36	SAPMQPCA	Display inspection method use	
QS37	SAPMQPCA	Central replacement of methods	
QS38	RQMTBV10	Display inspection method list	
QS39	SAPMSNUM	Maintain method number range	
QS41	SAPLQSBA	Maintain catalog	
QS41_EXT		Mapping for Code Groups and Codes	
QS42	SAPLQSBA	Display catalog	
QS43	SAPLQSBA	Maintain catalog	
QS44	SAPLQSBA	Maintain catalog	
QS45	SAPLQSBA	Display catalog	
QS46	SAPMQPBA	Display code group use	
QS47	SAPMQPBA	Central replacement of code groups	
QS48	RQSBAS40	Usage indicator - code groups	

QS49	SAPMQSEA	Display code groups and codes	
QS4A	SAPLQSPA	Display catalog	
QS51	SAPLQSKT	Edit Selected Sets	
QS52	SAPLQSKT	Display selected set index	
QS53	SAPLQSKT	Maintain individual selected set	
QS54	SAPLQSKT	Maintain selected set	
QS55	SAPLQSKT	Display selected set	
QS58	RQSBAS41	Usage indicator - selected sets	
QS59	SAPMQSEA	Display selected sets	
QS61	SAPMQMSP	Maintain material specification	
QS62	SAPMQMSP	Display material specification	
QS63	SAPMQMSP	Maintain material spec: Planning	
QS64	SAPMQMSP	Display material spec: For key date	
QS65	RQSPEZ10	Activate material specification	
QS66	RQJBCTRL	Plan activation of material spec.	
QS67	RQJBCTRL	Job overview: Activate mat. spec.	
QSFF		Customizing Template	
QSR5		Archive inspection plans	
QSR6	RQPREDE2	Delete routings	
QST01		Create Stability Study	

QST03	RQSTA003	Display Stability History	
QST04	RQSTA004	Display Inspection Plans	
QST05	RQSTA005	Graphical Scheduling Overview	
QST06	RQSTA006	Scheduling Overview (StabilityStudy)	
QST07	RQSTA007	Change Testing Schedule Items	
QST08	RQSTA007	Display Testing Schedule Items	
QST09	SAPLRMXT411	Maintain Planning Building Block	
QST10	SAPLRMXT411	Display Planning Module	
QSUB		Define subsystems	
QT00	MENUQT00	Test Equipment Management	
QT01	MENUQT01	Test equipment management	
QTSA	SAPLQUOS	Product Allocations: Send Quantities	
QTSP	SAPLQUOS	Product Allocations:Send Customizing	
QUERY_BP_FSBPBILDER	AQZZ/SAPQUERY/BPFSBP-BILDER===	BP: Screen Customizing for Query	
QV01		Create quality assurance agreement	
QV02		Change quality assurance agreement	
QV03		Display quality assurance agreement	
QV04		Find Quality Assurance Agreement	
QV11		Create technical delivery terms	
QV12		Change technical delivery terms	

QV13		Display technical delivery terms	
QV14		Search technical terms of delivery	
QV21		Create QA agreement (DocType Q03)	
QV22		Change Q-agreement (doc. type Q03)	
QV23		Display Q-agreement (doc. type Q03)	
QV24		Find Q-agreement (doc. type Q03)	
QV31		Create Q-spec. (doc.type Q04)	
QV32		Change Q-specification (docType Q04)	
QV33		Displ. Q-specification (docType Q04)	
QV34		Find Q-specification (doc. type Q04)	
QV51	SAPMQVDM	Create control for QM in SD	
QV52	SAPMQVDM	Change control for QM in SD	
QV53	SAPMQVDM	Display control for QM in SD	
QVM1	RQEVAM10	Inspection lots without completion	
QVM2	RQEVAM20	Inspection lots with open quantities	
QVM3	RQEVAM30	Lots without usage decision	
QZ00	MENUQZ00	Quality Certificates	
